Project: Burj Khalifa
Document: Snagging report
Time Range: 2026-09-07 to 2026-09-13
Compiled by: SACO

Snagging Report 2026-09-07 to 2026-09-13

18 snagging cases in range

Error types

Black point	18

Fix types (qty)

500mm VStick replacement	11
300mm VStick replacement	8
Jumper connection	1

Daily logs

2026-09-07

Location	Error type	Fix types	Comments
B09-105-103	Black point	500mm VStick replacement (1)	
B18-49-46	Black point	300mm VStick replacement (2)	
B20-52-50	Black point	500mm VStick replacement	

2026-09-08

Location	Error type	Fix types	Comments
B19-63-61	Black point	300mm VStick replacement (1)	

2026-09-10

Location	Error type	Fix types	Comments
C12-47-44	Black point	300mm VStick replacement (2)	

2026-09-11

Location	Error type	Fix types	Comments
C06-18-17	Black point	500mm VStick replacement	
C25-31-28	Black point	300mm VStick replacement	
C16-132-130	Black point	500mm VStick replacement	
CB01-102-100	Black point	500mm VStick replacement	
C07-39-37	Black point	500mm VStick replacement	
C13-75-73	Black point	500mm VStick replacement	
C13-121	Black point	Jumper connection	
B11-13-10	Black point	300mm VStick replacement	
C13-34-32	Black point	500mm VStick replacement	

2026-09-13

Location	Error type	Fix types	Comments
B23-71-68	Black point	300mm VStick replacement	
B10-99-97	Black point	500mm VStick replacement	
C09-99-97	Black point	500mm VStick replacement	
B23-60-58	Black point	500mm VStick replacement	