SACO

Project: Burj Khalifa
Document: Snagging report
Time Range: 2026-09-14 to 2026-09-20
Compiled by: SACO

Snagging Report 14/09/2026 to 20/09/2026

22 snagging cases in range

Error types

Black point	20
Flickering	1
Frozen	1

Fix types (qty)

500mm VStick replacement	18
300mm VStick replacement	10
Jumper replacement	1
Jumper connection	1

Daily logs

2026-09-14

Location	Error type	Fix types	Comments
C19-49-46	Black point	300mm VStick replacement (1)	
C07-105-103	Black point	500mm VStick replacement (1)	
C12-111-109	Black point	500mm VStick replacement (1)	
C25-49-46	Black point	500mm VStick replacement (1), Jumper replacement (1)	

2026-09-15

Location	Error type	Fix types	Comments
B16-9-8	Black point	300mm VStick replacement (1), 500mm VStick replacement (1)	
B02-134-133	Black point	500mm VStick replacement (1)	
B15-58-55	Black point	300mm VStick replacement (1), 500mm VStick replacement (1)	

2026-09-16

Location	Error type	Fix types	Comments
C14-99-97	Black point	500mm VStick replacement (2)	

2026-09-17

Location	Error type	Fix types	Comments
C11-80-78	Black point	Jumper connection	
B27-25-23	Flickering	500mm VStick replacement (1)	
C03-31	Black point	300mm VStick replacement (1)	

2026-09-18

Location	Error type	Fix types	Comments
B04-51-49	Black point	300mm VStick replacement (1)	
C10-62-59	Black point	300mm VStick replacement (1)	
CB01-78-74	Frozen	500mm VStick replacement (1)	
B14-16-14	Black point	500mm VStick replacement (1)	
C04-13-10	Black point	300mm VStick replacement (1), 500mm VStick replacement (2)	

Location	Error type	Fix types	Comments
C23-60-57	**Black point**	**300mm VStick replacement (1)**	

2026-09-19

Location	Error type	Fix types	Comments
C13-72-70	Black point	500mm VStick replacement (1)	
B19-9-8	Black point	300mm VStick replacement (1), 500mm VStick replacement (1)	
B06-54-52	Black point	300mm VStick replacement (1)	
B19-83-81	Black point	500mm VStick replacement (1)	

2026-09-20

Location	Error type	Fix types	Comments
C20-98-97	Black point	500mm VStick replacement (2)	


Photos

Snagging pictures grouped by day. The caption shows the incident location.


2026-09-14




C19-49-46
Case #42203



C07-105-103
Case #42204




C12-111-109
Case #42205




C25-49-46
Case #42206

2026-09-15



B16-9-8
Case #42207




B02-134-133
Case #42208



B15-58-55
Case #42209

2026-09-16



C14-99-97
Case #42210

2026-09-17



C11-80-78
Case #42211



B27-25-23
Case #42212




C03-31
Case #42213

2026-09-18




B04-51-49
Case #42214



C10-62-59
Case #42215



CB01-78-74
Case #42216



B14-16-14
Case #42217



C04-13-10
Case #42218



C23-60-57
Case #42219


2026-09-19




C13-72-70
Case #42220



B19-9-8
Case #42221




B06-54-52
Case #42222



B19-83-81
Case #42223

2026-09-20



C20-98-97
Case #42239