Project: Burj Khalifa
Document: Snagging report
Time Range: 2026-10-19 to 2026-10-25
Compiled by: SACO

Snagging Report 19/10/2026 to 25/10/2026

12 snagging cases in range

Error types

Black point	12

Fix types (qty)

500mm VStick replacement	8
300mm VStick replacement	6

Daily logs

2026-10-19

Location	Error type	Fix types	Comments
C05-111bmu	Black point	500mm VStick replacement (1)	

2026-10-20

Location	Error type	Fix types	Comments
C12-54-52	Black point	500mm VStick replacement (1)	

2026-10-21

Location	Error type	Fix types	Comments
C22-42-40	Black point	500mm VStick replacement (1)	
C07-72-70	Black point	300mm VStick replacement (1)	
C20-98-97	Black point	500mm VStick replacement (1)	
C07-75-73	Black point	300mm VStick replacement (1)	
C22-32-29	Black point	300mm VStick replacement (2), 500mm VStick replacement (1)	
C23-42-40	Black point	500mm VStick replacement (1)	

2026-10-22

Location	Error type	Fix types	Comments
B7-78-76	Black point	300mm VStick replacement (1)	
C26-33	Black point	500mm VStick replacement (1)	


2026-10-23

Location	Error type	Fix types	Comments
C4-13-10	Black point	500mm VStick replacement (1)	
C36-22-19	Black point	300mm VStick replacement (1)	

Photos


Snagging pictures grouped by day. The caption shows the incident location.

2026-10-19




C05-111bmu
Case #42298

2026-10-20



C12-54-52
Case #42301


2026-10-21



C22-42-40
Case #42302



C07-72-70
Case #42303



C20-98-97
Case #42304



C07-75-73
Case #42305



C22-32-29
Case #42306



C23-42-40
Case #42307

2026-10-22



B7-78-76
Case #42311



C26-33
Case #42312

2026-10-23



C4-13-10
Case #42313

1 case has no photo available.